


# 2017 FORD Mustang - VIN 1FA6P8CF0H5202343



<b>Odometer</b> No problems found		<b>Open Safety Recalls</b> 4 problems found	
<b>Accidents</b> No problems found		<b>Mileage</b> No data	
<b>Sales history</b> No records found		<b>TWO+ Owners</b>	

Year  
**2017**

Trim  
**GT Coupe**

Steering type  
**Left-hand Drive (lhd)**

Standard Seating  
**4**

Make  
**Ford**

Engine  
**5l V-shaped 5.0l 4v Premium Fuel**

Fuel Type  
**Gasoline**

Model  
**Mustang**

Made in  
**United States (usa)**

Body Style  
**Coupe**

## Odometer check

No problem reported

CONFIRMED DATA  
**CHECK NOW**

<b>Odometer:</b> Not Actual		No problems found
<b>Odometer:</b> Tampering Verified		No problems found
<b>Odometer:</b> Exempt from Odometer Disclosure		No problems found
<b>Odometer:</b> Exceeds Mechanical Limits		No problems found
<b>Odometer:</b> May be Altered		No problems found
<b>Odometer:</b> Replaced		No problems found
<b>Odometer:</b> Reading at Time of Renewal		No problems found
<b>Odometer:</b> Discrepancy		No problems found
<b>Odometer:</b> Call Title Division		No problems found
<b>Odometer:</b> Exceeds Mechanical Limits Rectified		No problems found

Data	Mileage
Source	History records

## Open safety recall check

4 problems reported

CONFIRMED DATA  
**CHECK NOW**

**Feb 16, 2022**  
22V082000

**BACK OVER PREVENTION: SENSING SYSTEM: CAMERA**  
Ford Motor Company (Ford) is recalling certain 2015-2017 Mustang vehicles. The rearview camera wiring may be loose or damaged, which can result in a blank or distorted image.

**Aug 30, 2017**  
17V529000

**AIR BAGS:FRONTAL:PASSENGER SIDE:INFLATOR MODULE**

Ford Motor Company (Ford) is recalling certain 2017 F-150 and Mustang vehicles. The air bag inflator within the passenger frontal air bag module may rupture in the event of a crash.

**Mar 16, 2017**  
17V168000

**LATCHES/LOCKS/LINKAGES:DOORS:LATCH**

Ford Motor Company (Ford) is recalling certain 2017 Ford Mustang vehicles. The return spring for the driver side interior door handle may come loose, allowing the driver's door to unlatch in a side impact crash. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 206, "Door Locks and Door Retention Components."

**Oct 26, 2016**  
16V779000

**ENGINE AND ENGINE COOLING:COOLING SYSTEM:HOSES/LINES/PIPING/FITTINGS**

Ford Motor Company (Ford) is recalling certain model year 2015-2017 Mustang vehicles manufactured February 24, 2015, to August 30, 2016. A hose may separate from the engine oil cooler tube assembly causing an oil leak.

## Stolen vehicle check

✔ No problem reported


CONFIRMED DATA  
**CHECK NOW**

## Vehicle damages

CONFIRMED DATA  
**CHECK NOW**

This section lists reported damages to this vehicle. You can use this information as leverage when negotiating the price of the car. If the damages are excessive, consider a different vehicle

No damages




## Market price analysis

CONFIRMED DATA  
**CHECK NOW**

### Classified sites price range


Like if you buy the car from dealership




Market price analysis is based on a vehicle's history such as vehicle class and age, number of owners, accident and damage history, title brands, odometer readings, etc. This information is used to compare the vehicle's favorability against the entire market of vehicles with

### Auction price range

Near the price the dealer buy this vehicle




Price/Year Dependence



Price



Price/Mileage Dependence



## Ownership cost

### Depreciation

Year 1 <b>\$2,336</b>	Year 2 <b>\$2,156</b>	Year 3 <b>\$1,976</b>
Year 4 <b>\$1,797</b>	Year 5 <b>\$1,617</b>	
Sum for 5 years <b>\$9,882</b>		



### Insurance

Year 1 <b>\$1,932</b>	Year 2 <b>\$2,000</b>	Year 3 <b>\$2,070</b>
Year 4 <b>\$2,142</b>	Year 5 <b>\$2,217</b>	
Sum for 5 years <b>\$10,361</b>		



### Fuel

Year 1 <b>\$1,418</b>	Year 2 <b>\$1,461</b>	Year 3 <b>\$1,512</b>
Year 4 <b>\$1,572</b>	Year 5 <b>\$1,643</b>	
Sum for 5 years <b>\$7,606</b>		



### Maintenance

Year 1 <b>\$2,763</b>	Year 2 <b>\$2,142</b>	Year 3 <b>\$1,356</b>
Year 4 <b>\$1,742</b>	Year 5 <b>\$2,291</b>	
Sum for 5 years <b>\$10,294</b>		



**Repair**

Year 1	Year 2	Year 3
\$1,067	\$1,221	\$1,393
Year 4	Year 5	
\$1,511	\$1,730	
Sum for 5 years		
<b>\$6,922</b>		



**Taxes & Fees**

Year 1	Year 2	Year 3
\$1,722	\$196	\$250
Year 4	Year 5	
\$160	\$222	
Sum for 5 years		
<b>\$2,550</b>		



**Total for 5 years:**  
**\$47,615**